



Certificate no. TC-6229

Electrical Research & Testing organisation™

(Accredited by the National Accreditation Board for Testing and Calibration Laboratories, Govt. Of India)

Plot No. 747, Manjusar Village, B/H Gurukrupa Farm, Savli-Vadodara Road, Ta.: Savli, Dist.: Vadodara,

Pin Code : 391775. Gujarat, India.

Telephone : 02667-264007, +91 88660 09021

Email : erto@erto.in / sr.patel@erto.in

Web : http://www.erto.in



ERTO

Quality Assurance Laboratory



TEST REPORT

Report No	: ERTO/TRP/2021/0131
ULR No.	: TC62292000000300F
Date of issue	: 29/06/2020
Total number of pages	: 25
Customer's name	: PVJ POWER SOLUTIONS
Address	: Vill. Nasrali, Post- Dabhota, Bharatgarh Road, Nalagarh (HP).
Customer's reference & date	: Email, dated 17/06/2020
Test specification	
-Standard	: As per IS 1180 (Part 1):2014 with all amendments
-Test procedure	: As per IS 1180 (Part 1):2014 with all amendments
-Non-standard test method	: N/A
ERTO sample ID no.	: ERTO-0126
Test performed at	: ERTO lab
Name of test sample	: 2500 kVA, Distribution Transformer
Make	: PVJ POWER SOLUTIONS
Rating	: 2500 kVA
Technical specification of test sample	: As per page 2.
Test performed	: As per page 5.
Any other details specified by customer: ---	
Date of receipt of test sample	: 24/06/2020
Condition on Receipt	: Good
Date(s) of performance of test(s)	: 24/06/2020 to 29/06/2020
Tests witnessed by	: Mr. R.K. ASTHANA (G.M. Technical, M/s. PVJ POWER SOLUTIONS)
List of Enclosures	
-Test sample photo	: As per page 3.
-Rating plate photo	: As per page 4.
-Drawings (As submitted by customer)	: 1) PVJ-2500L3/02 Rev. 01 2) PVJ-2500L3/01 SH. 1/1
Remarks	
1) The sample conforms to the requirements of above mentioned standard for the test nos. 2, 5, 6 & 8 to 14.	
2) The observations of the test nos. 1, 3, 4 & 7 are as per page 6 to 9.	
Prepared By	Checked By (S.B. Diwan)
	Approved By (S.R. Patel) (Technical Director)
Notes:	
1. This report relates only to the particular sample tested.	
2. Only the tests asked by the customer have been carried out.	
3. This report cannot be reproduced in part under any circumstances.	
4. Publication of this report requires prior permission in writing from Technical Director, ERTO.	
5. In case of any dispute, ERTO will be the exclusive jurisdiction & shall be construed as where the cause has arisen.	
Caution: ERTO is not responsible for the authenticity of photocopied or reproduced test reports. ERTO provides support to customers for verification of the authenticity of test reports issued by ERTO.	

TE-A 029120