



Certificate no. TC-6229

Electrical Research & Testing organisationTM

(Accredited by the National Accreditation Board for Testing and Calibration Laboratories, Govt. Of India)

Plot No. 747, Manjusar Village, B/H Gurukrupa Farm, Savli-Vadodara Road, Ta.: Savli, Dist.: Vadodara.

Pin Code : 391775, Gujarat, India.

Telephone : 02667-264007, +91 88660 09021

Email : erto@erto.in / sr.patel@erto.in

Web : http://www.erto.in

**ERTO**

Quality Assurance Laboratory



TEST REPORT

Report No	: ERTO/TRP/1819/0091
Date of issue	: 29/06/2018
Total number of pages	: 19
Customer's name	: PVJ POWER SOLUTIONS
Address	: Nalagarh Bharatgarh Road PO Dabhota, Nalagarh, HP-174101.
Customer's reference & date	: PVJ/GM/2018-09, dated 21/06/2018
Test specification	
-Standard	: As per IS 1180 (Part 1):2014
-Test procedure	: As per IS 1180 (Part 1):2014 with amendment no. 1 & 2, IS 2026 (Part 1):2011, IS 2026 (Part 3):2009
-Non-standard test method	: N/A
ERTO sample ID no.	: ERTO-0168
Test performed at	: ERTO lab
Name of test sample	: 315 kVA, Distribution Transformer
Make	: PVJ POWER SOLUTIONS
Rating	: 315 kVA
Technical specification of test sample	: As per page 2 of 19.
Test performed	: As per page 5 of 19.
Any other details specified by customer:	---
Date of receipt of test sample	: 23/06/2018
Condition on Receipt	: Good
Date(s) of performance of test(s)	: 25/06/2018 to 29/06/2018
Witnessed by	: Mr. R.K. Asthana (GM-Technical, PVJ Power Solutions)
List of Enclosures	
-Test sample photo	: As per page 3 of 19.
-Rating plate photo	: As per page 4 of 19.
-Drawings (As submitted by customer)	: 1) PVJ/315/01-A 2) PVJ/315/01-B REV 00 SHEET NO. 1 OF 1 3) PVJ/315/02
Remarks	: 1) The sample conforms to the requirements of above mentioned standard for the test nos. 2, 5, 6 & 8 to 14. 2) The observations of the test nos. 1, 3, 4 & 7 are as per page 6 of 19 to page 9 of 19.
Prepared By	(Prana Himanshu H.)
Checked By	(S.B.Diwan)
Approved By	(S.R.Patel) (Technical Director)
Notes:	1. This report relates only to the particular sample tested. 2. Only the tests asked by the customer have been carried out. 3. This report cannot be reproduced in part under any circumstances. 4. Publication of this report requires prior permission in writing from Technical Director, ERTO. 5. In case of any dispute, ERTO will be the exclusive jurisdiction & shall be construed as where the cause has arisen.
Caution:	ERTO is not responsible for the authenticity of photocopied or reproduced test reports. ERTO provides support to customers for verification of the authenticity of test reports issued by ERTO.

TE-A 002618